# **Battery certificate**

Date of diagnosis : 22/05/2025 at 17:34 Europe/Paris






## Hyundai Kona <sup>(1)</sup>

VIN : KMHK581GUNU145782 Date of first registration : 01/01/2022 Mileage : 49,711 miles

<sup>(1)</sup> According to the statement of the person who carried out the diagnosis

#### **Battery status**



Remaining usable capacity / Usable capacity when new<sup>(3)</sup>

#### 60.61 kWh / 64 kWh

<sup>(2)</sup> SOH generated from vehicle own data, as considered for the manufacturer's warranty.
<sup>(3)</sup> Useful capacity is the battery's actual available capacity. It may differ from the capacity communicated by the manufacturer.

### Manufacturer's warranty

We invite you to take a look at the warranty conditions for your battery: duration, mileage, number of cycles. As an indication, the average warranty observed in Europe for this vehicle is as follows: SOH greater than 70%, for 8 years or 120,000 miles.

Range	(4)
-------	-----

Orban use

Highway use

Mixed use

☆ Summer (25°C)

302 - 334 miles 219 - 242 miles

270 - 299 miles

& Winter (0°C)

231 - 255 miles

188 - 208 miles

218 - 241 miles

<sup>(4)</sup> Ranges calculated using the Moba consumption model, based on WLTP cycles.



